

Plockton & District Community Council

Current Roads & Related Issues

March 2017

Issue	First Reported	Comments
Duirinish Bridge in need of repair	July 2016	done
Streetlights not working in Duirinish	January 2017	
Bad potholes on road around airstrip	January 2016	Patching will be done when they are working in the village
Cattle grid at Burnside very noisy (needs dampened)	July 2016	Rubber seal to be installed
Road sign removed from foot of Strathie – needs replaced	October 2016	New sign will be ordered
School Railway Bridge safety: Continued concern about the safety of the school railway crossing, noting the lack of action on speed bumps, green 'pavement' and signs warning of on-coming vehicles in road, when exiting the village.	November 2015	Speed bumps to be heightened and sign – oncoming traffic in middle of road – to be erected on village side
Two lowered pavement sections to be installed in harbour street for wheelchair access.	November 2014	done
Wee Strathie' (i.e. hill from Plockton to Duncraig): Lack of roadside drainage leading to surface water and ice on road.	December 2016	Will be added to programme
Roadside gulleys needing cleared on road down from High School into village to prevent standing water on road.	December 2016	done
Standing water on Harbour street outside Rod Macleod's house (Struan).	December 2016	
Erbusaig Road - re-surfacing needed.	January 2017	Will start on Wednesday 1st March – hasn't happened yet
Innes Street re-surfacing needed.	January 2017	Before Easter
Harbour Street – patching required.	January 2017	Before Easter
Pavements outside hotel and Inn need attention	January 2017	Before Easter

Weed treatment for walls and kerbs in the village	January 2017	
Whins on road side on Duirnish straight		Will be cut
Leaves lying on pavement up to Frithard Road	October 2016	Will be removed by sweeper
New passing place in space before Achnadarach turnoff	January 2017	Roadside will be tarred
Ramp in road just past Achnadarach turn-off	January 2017	Will be repaired at the same time
Passing places on Achmore back road – deep ditches on side of the road	January 2017	Safety barrier erected
Hole in carpark wall on shore side, coving stones missing	October 2016	Duncan MacRae to be asked to give a quote for repair
Bus shelter in Duirnish to be moved		Morag will advise as to position
20 mph signs in Duirnish – and signs to be moved further back on approach from Plockton		This will require a legal action