## **Plockton & District Community Council**

## **Current Roads & Related Issues**

## September 2017

Issue	First Reported	Comments
Duirnish Bridge in need of repair	July 2016	Done, but far side still to be repaired
Streetlights not working in Duirnish	January 2017	done
Bad potholes on road around airstrip	January 2016	Patching will be done when they are working in the village – some work has been done
Cattle grids at Burnside and in Duirnish very noisy (needs dampened)	July 2016	Rubber seal to be installed – no action so far
Road sign removed from foot of Strathie – needs replaced	October 2016	New sign will be ordered – no action so far
School Railway Bridge safety: Continued concern about the safety of the school railway crossing, noting the lack of action on speed bumps, green 'pavement' and signs warning of on-coming vehicles in road, when exiting the village.		Speed bumps to be heightened and sign – oncoming traffic in middle of road – to be erected on village side – no action so far
Two lowered pavement sections to be installed in harbour street for wheelchair access.	November 2014	done
Wee Strathie' (i.e. hill from Plockton to Duncraig): Lack of roadside drainage leading to surface water and ice on road.	December 2016	Will be added to programme  – no action so far
Roadside gulleys needing cleared on road down from High School into village to prevent standing water on road.	December 2016	done
Standing water on Harbour street outside Rod Macleod's house (Struan).	December 2016	
Erbusaig Road - re-surfacing needed.	January 2017	Will start on Wednesday 1st March – this has been done

Innes Street re-surfacing needed.	January 2017	Before Easter – no action so far
Harbour Street – patching required.	January 2017	Before Easter – no action so far
Pavements outside hotel and Inn need attention	January 2017	Before Easter – no action so far
Weed treatment for walls and kerbs in the village	January 2017	No weedkiller treatment this summer in Plockton
Whins on road side on Duirnish straight		Will be cut – small improvement
Leaves lying on pavement up to Frithard Road	October 2016	Will be removed by sweeper
New passing place in space before Achnadarach turnoff	January 2017	Roadside will be tarred – no action so far
Ramp in road just past Achnadarach turn-off	January 2017	Will be repaired at the same time no action so far
Passing places on Achmore back road – deep ditches on side of the road	January 2017	Safety barrier erected, but deep ditches still a problem
Hole in carpark wall on shore side, coving stones missing	October 2016	Duncan MacRae to be asked to give a quote for repair – no action so far
Bus shelter in Duirnish to be moved		Morag will advise as to position: opposite Drumfearn and Clachan Cottage
White lines on Inisruaraidh, particularly coming up to the summit.	September 2017	
Trees at Strathy Road junction impeding view	September 2017	
Duirnish Station road and Barleyport Road needing repairs	September 2017	
More warning signs for Duirnish about animals and livestock	September 2017	
20 mph signs in Duirnish – and signs to be moved further back on approach	n	This will require a legal

from Plockton	action, but only if they are
	moved more than